

EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S143	10085	((244/1r,ln,159.1,171.7,117r,117a,119,121,129.2,131) or (52/404.2,404.4,407.4,512,dig.6) or (411/383,439,455,487,508,509,510,512,903,913) or (24/16pb,102t,114.3,297,453,581.1)).COLS.	US_PGPUB; USPAT	OR	OFF	2011/03/31 09:45
S144	292	S143 AND @PD >= "20100708"	US_PGPUB; USPAT; USOCR	OR	ON	2011/03/31 09:45
S145	13	((("5759659") or ("6627561") or ("6177157") or ("6231944") or ("7083142") or ("7282252") or ("5987833") or ("3003902") or ("2342839") or ("5298694") or ("6358591") or ("3567162") or ("20050211839")).PN.	US_PGPUB; USPAT	OR	OFF	2011/03/31 10:36
S146	15	((("1134479") or ("1164006") or ("9112131")).PN.	FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2011/03/31 10:45
S147	1	"9112131"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2011/03/31 10:51
S148	16496	((insulation OR liner OR lining OR barrier) WITH (fireproof OR fireblock OR ((fire OR flame OR heat OR burn OR burnthrough) NEAR3 (proof OR resist\$3 OR block\$3 OR retard\$3)))	US_PGPUB; USPAT; USOCR	OR	ON	2011/03/31 12:00
S149	448	S148 SAME (fuselage OR aircraft OR airliner OR aeroplane OR aerodyne OR ((air OR aero OR aerial) ADJ vehicle))	US_PGPUB; USPAT; USOCR	OR	ON	2011/03/31 12:01
S150	5971	((fastener OR fastening OR attachment OR bolt OR nut OR washer OR stud OR post) WITH (fireproof OR fireblock OR ((fire OR flame OR heat OR burn OR burnthrough) NEAR3 (proof OR resist\$3 OR block\$3 OR retard\$3)))	US_PGPUB; USPAT; USOCR	OR	ON	2011/03/31 12:02
S151	40	S149 AND S150	US_PGPUB; USPAT; USOCR	OR	ON	2011/03/31 12:03
S155	70	((mueller NEAR3 rainer) OR (turanski NEAR3 peter) OR (oestreich NEAR3 wilko) OR (reinelt NEAR3 thorsten)).in.	US_PGPUB; USPAT; USOCR	OR	ON	2011/03/31 12:12

S156	6	S155 AND S148	US- PGPUB; USPAT; USOCR	OR	ON	2011/03/31 12:13
------	---	---------------	-------------------------------	----	----	---------------------

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S157	11	((244/1r,1n,159.1,171.7,117r,117a,119,121,129.2,131) or (52/404.2,404.4,407.4,512,dig.6) or (411/383,439,455,487,508,509,510,512,903,913) or (24/16pb,102t,114.3,297,453,581.1)).OLCS.	UPAD	OR	OFF	2011/03/31 12:15
S158	229721	(insulation OR liner OR lining OR barrier).CLM.	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:15
S159	40359	(fireproof OR fireblock OR ((fire OR flame OR heat OR burn OR burnthrough) NEAR3 (proof OR resist\$3 OR block\$3 OR retard\$3))).CLM.	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:16
S160	39662	(fuselage OR aircraft OR airliner OR aeroplane OR aerodyne OR ((air OR aero OR aerial) ADJ vehicle)).CLM.	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:16
S161	613356	(fastener OR fastening OR attachment OR bolt OR nut OR washer OR stud OR post).CLM.	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:16
S162	26	S158 AND S159 AND S160 AND S161	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:16
S163	2502	S158 SAME S159	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:17
S164	1107	S161 SAME S159	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:17

S166	7	S163 AND S164 AND S160	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:17
S168	3	"burn-through-proof".CLM.	US- PGPUB; USPAT; UPAD	OR	ON	2011/03/31 12:18

3/31/2011 12:19:28 PM

C:\Documents and Settings\rgreen1\My Documents\EAST\Workspaces\10596982.wsp